

HP-41C Return Test Program by Keith Jarett
PPC Calculator Journal V7 N7 P19 Sept 1980

```
01 LBL "RTNTST" ;Return Test Program
02 XEQ 01
03 0
04 PSE
05 RTN
06 LBL 01
07 XEQ 02
08 1
09 PSE
10 RTN
11 LBL 02
12 XEQ 03
13 2
14 PSE
15 RTN
16 LBL 03
17 XEQ 04
18 3
19 PSE
20 RTN
21 LBL 04
22 XEQ 05
23 4
24 PSE
25 RTN
26 LBL 05
27 9
28 ENTER
29 2
30 XEQ "XRTN" ;V7N7P18 SIGMA (Line 315)
31 FC?C 09
32 GTO 95
33 XEQ 06
34 9
35 ENTER
36 2
37 XEQ "RRTN" ;V7N7P18 SIGMA (Line 303)
38 LBL 95
39 5
40 PSE
41 RTN
42 LBL 06
43 XEQ 07
44 6
45 PSE
46 RTN
47 LBL 07
48 XEQ 08
49 7
50 PSE
51 RTN
52 LBL 08
53 XEQ 09
54 8
55 PSE
56 RTN
57 LBL 09
58 XEQ 10
59 9
60 PSE
61 RTN
62 LBL 10
63 8
64 ENTER
65 6
66 XEQ "XRTN" ;V7N7P18 SIGMA (Line 315)
67 FC?C 08
```

68 GTO 96
69 XEQ 11
70 8
71 ENTER
72 6
73 XEQ "RRTN" ;V7N7P18 SIGMA (Line 303)
74 LBL 96
75 10
76 PSE
77 RTN
78 LBL 11
79 XEQ 12
80 11
81 PSE
82 RTN
83 LBL 12
84 XEQ 13
85 12
86 PSE
87 RTN
88 LBL 13
89 XEQ 14
90 13
91 PSE
92 RTN
93 LBL 14
94 XEQ 15
95 14
96 PSE
97 RTN
98 LBL 15
99 XEQ 16
100 15
101 PSE
102 RTN
103 LBL 16
104 16
105 PSE
106 RTN
107 END

00BBC000F70052544E545354E0000110898502E00002118985
03E0000312898504E0000413898505E0000514898506198312
1EF45852544EAB09D0005FE000061983121EF45252544ECF5F
15898507E0000716898508E0000817898509E000091889850A
E0000A1989850B1883161EF45852544EAB08D00060E0000B18
83161EF45252544ECF60111089850CE0000C111189850DE000
0D111289850EE0000E111389850FE0000F11148985CF0FE000
1011158985CF1011168985C0000DEE

187 BYTES

HP-41C Return Test Program by Keith Jarett PPC V7 N7 P19 Sept 1980

Program Registers Needed: 27

Row 1 (1 - 2)



Row 2 (3 - 12)



Row 3 (12 - 22)




Row 4 (22 - 30)



Row 5 (30 - 36)



Row 6 (37 - 43)



Row 7 (43 - 52)



Row 8 (53 - 61)



Row 9 (62 - 68)




Row 10 (68 - 73)



Row 11 (73 - 80)



Row 12 (81 - 89)



Row 13 (89 - 97)



Row 14 (98 - 104)



Row 15 (105 - 107)

