

# HP-41C Wand E & F Append Nulls PPC V8 N3 P22 May 1981

THESE SHOULD WORK ON E & F WANDS


HEX F0717F APPEND 0 NULLS




HEX F1727F00 APPEND 1 NULL



HEX F2737F0000 APPEND 2 NULLS



HEX F3747F000000 APPEND 3 NULLS




HEX F4757F00000000 APPEND 4 NULLS




HEX F5767F0000000000 APPEND 5 NULLS




HEX F6777F000000000000 APPEND 6 NULLS




HEX F7787F00000000000000 APPEND 7 NULLS




HEX F8797F0000000000000000 APPEND 8 NULLS




HEX F97A7F000000000000000000 APPEND 9 NULLS



HEX FA7B7F00000000000000000000 APPEND 10 NULLS



HEX FB7C7F0000000000000000000000 APPEND 11 NULLS



HEX FC7D7F000000000000000000000000 APPEND 12 NULLS



HEX FD7E7F00000000000000000000000000 APPEND 13 NULLS



HEX FE7F7F0000000000000000000000000000 APPEND 14 NULLS

